

EXERCISE 2-6

Using the SAM Program, determine the dimensions of a four bars mechanism which allows to put a tool on the three holes of the following part:




Figure E2.3.- Tooling holes in a part.